



Picture of old dryers and coils



Picture of dryer vents with frost prior to replacement of dryers



Broken dryer coils prior to replacing dryers



Piping of dryer coils prior to replacing with new dryers



Picture showing air temp of dryer on a cold day prior to installation of air damper.



The old dryers prior to replacement with new dryers

